

Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 12/28/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the access road.



Inspection Photos



Photo 2. Facing northwest toward the loction.



Inspection Photos



Photo 3. There is a topsoil pile stored and stabilized at the west side of the location. Approximately 270' x 20'.



Inspection Photos



Photo 4. Facing east at the location.



Inspection Photos



Photo 5. Facing southeast. There is a perimeter silt fence installed around the location.



Inspection Photos



Photo 6. North side of the location facing southwest.

