

Inspection Photos
Location Name: TREBOR B/11-21
Location ID: 414334



Photo #1

Trebor B 11-21 (123-30729) Wellsite
Temporarily Abandoned | TA
CA: Overgrown Vegetation
prior photo



Photo #2

Trebor B 11-21 Wellsite
Temporarily Abandoned | TA
Overgrown Vegetation, NOW mitigated
Date: 12-14-2023 (Operator photo)



Inspection Photos
Location Name: TREBOR B/11-21
Location ID: 414334



Photo #3

Trebor B11-6, 11-3, 11-18, 11-20, 11-21 Battery site

Inactive | Shut-down

Formerly served:

Trebor B11-4, B 11-19 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 326889

prior photo

