

Inspection Photos

12/27/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334935

Inspection Doc: 696205499

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 1: Photos taken from the west end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 3: Photo taken from the pipeline equipment on the west end of the Location. Leak evident at equipment. Photo right shows fluids spilled into containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 4: Photo example of what appears to be Musk or Bull thistle remnants observed on the Location. Management efforts by Operator apparent on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 5: Photo example showing interim areas on the southern end of the Location that do not appear to be progressing towards 1003 standards; vegetation observed is predominantly undesirable plant species such as cheatgrass.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334935



Photo 6: Photo show uncapped riser on the southeastern interim areas of the Location. Riser is considered unused equipment and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources