

Inspection Photos
Location Name: TREBOR B/11-18
Location ID: 414330



Photo #1

Trebor B 11-18 (123-30730) Wellsite

Temporarily Abandoned | TA

CA: Overgrown Vegetation

prior photo



Photo #2

Trebor B 11-18 Wellsite

Temporarily Abandoned | TA

Overgrown Vegetation, NOW mitigated

Date: 12-08-2023 (Operator photo)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: TREBOR B/11-18

Location ID: 414330



Photo #3

Trebor B11-6, 11-3, 11-18, 11-20, 11-21 Battery site

Inactive | Shut-down

Formerly served:

Trebor B11-4, B 11-19 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 326889

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources