

Inspection Photos

Loc: 307392

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/26/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. Facing northwest toward the wellhead.



Inspection Photos



Photo 3. Facing northeast toward the reclaimed flowline.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307392 | Date: 12/26/2023

Inspection Photos



Photo 4. Facing southeast toward the well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307392 | Date: 12/26/2023

Inspection Photos



Photo 5. Facing south toward poly line that goes to offsite pit south of the location. The offsite pit was not inspected.

