

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF11A-28 C28A 595 Pad

Location #: 335970



Photo # 1283 From entrance to location



Photo # 1284 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF11A-28 C28A 595 Pad

Location #: 335970



Photo # 1285 Location/blowdown tank



Photo # 1286 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF11A-28 C28A 595 Pad

Location #: 335970



Dec 28, 2023 at 1:23:17 PM



Dec 28, 2023 at 1:24:26 PM

Photo # 1287 Location

Photo # 1288 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF11A-28 C28A 595 Pad

Location #: 335970



Photo # 1289 Location



Photo # 1290 Wellhead signs lack required information



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF11A-28 C28A 595 Pad

Location #: 335970



Photo # 1291 Wellhead signs lack required information