

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF04D D28 595 Pad

Location #: 335822



Photo # 1251 From entrance to location



Photo # 1252 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF04D D28 595 Pad

Location #: 335822



Photo # 1253 Location



Photo # 1254 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF04D D28 595 Pad

Location #: 335822




Photo # 1255 Location



Photo # 1256 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF04D D28 595 Pad

Location #: 335822




Photo # 1257 Location




Photo # 1258 Open piping/wildlife hazard



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF04D D28 595 Pad

Location #: 335822



Photo # 1259 Wellhead signs lack required information



Photo # 1260 Wellhead signs lack required information

