

Inspection Photos

Location Name: CAERUS PICEANCE LLC EF I30 595 Pad

Location #: 335588



Photo # 1102 From entrance to location



Photo # 1103 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EF I30 595 Pad

Location #: 335588



Photo # 1104 Location



Photo # 1105 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC EF I30 595 Pad
Location #: 335588



Dec 28, 2023 at 11:30:58 AM

Photo # 1106 Location



Dec 28, 2023 at 11:31:43 AM

Photo # 1107 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC EF I30 595 Pad
Location #: 335588




Photo # 1108 Location



Photo # 1109 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EF I30 595 Pad

Location #: 335588



Photo # 1110 Location



Photo # 1111 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EF I30 595 Pad

Location #: 335588



Dec 28, 2023 at 11:37:17 AM

Photo # 1112 Location



Dec 28, 2023 at 11:37:59 AM

Photo # 1113 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EF I30 595 Pad

Location #: 335588



Photo # 1114 Wellhead signs lack required information



Photo # 1115 Wellhead signs lack required information



Inspection Photos
Location Name: CAERUS PICEANCE LLC EF I30 595 Pad
Location #: 335588



Photo # 1116 Wellhead signs lack required information



Photo # 1117 Wellhead signs lack required information

Inspection Photos
Location Name: CAERUS PICEANCE LLC EF I30 595 Pad
Location #: 335588



Photo # 1118 Ground fissure/wildlife & personnel hazard



Photo # 1119 Ground fissure/wildlife & personnel hazard

Inspection Photos
Location Name: CAERUS PICEANCE LLC EF I30 595 Pad
Location #: 335588




Photo # 1120 Ground fissure/wildlife & personnel hazard




Photo # 1121 Ground fissure/wildlife & personnel hazard