

Inspection Photos
Location Name: Wells Ranch USX AA 13-08
Location ID: 302389



Photo 1 – Wellsite



Photo 2 – 1" Unmarked Riser

Inspection Photos
Location Name: Wells Ranch USX AA 13-08
Location ID: 302389



Photo 3 – Wellhead



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Wells Ranch USX AA 13-08
Location ID: 302389



Photo 5 – Unused Secondary Containment



Photo 6 – 1" Unmarked Risers

Inspection Photos
Location Name: Wells Ranch USX AA 13-08
Location ID: 302389



Photo 7 – 1” Unmarked Riser