

**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 1 Wellsite.**



**Photo 2 WH sign faded and needs replaced.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**




**Photo 3 Wellhead overrun with dead undesirable vegetation and trash.**



**Photo 4 Wellhead overrun with dead undesirable vegetation and trash.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 5 Wellhead overrun with dead undesirable vegetation and trash.**



**Photo 6 Wellsite overrun with dead undesirable vegetation and trash.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 7 Unused Ancillary equip. overrun with dead undesirable vegetation.**



**Photo 8 Unused Ancillary equip. overrun with dead undesirable vegetation.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 9 Wellsite overrun with dead undesirable vegetation & trash.**



**Photo 10 Horizontal Heated Separator overrun with dead undesirable vegetation.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 11 Horizontal Heated Separator overrun with dead undesirable vegetation & trash.**



**Photo 12 Horizontal Heated Separator overrun with dead undesirable vegetation.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 13 Valved Flow line overrun with dead undesirable vegetation & trash.**



**Photo 14 Unused aux pump overrun with dead undesirable vegetation & trash.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 15 TB sign, TB berm is overrun with dead undesirable vegetation & trash.**



**Photo 16 TB overrun with dead undesirable vegetation & trash.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 17 TB berm is overrun with dead undesirable vegetation.**



**Photo 18 TB overrun with dead undesirable vegetation.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 19 TB berm is overrun with dead undesirable vegetation.**



**Photo 20 TB overrun with dead undesirable vegetation.**



**Inspection Photos**  
**Location Name: Glen Horton 1**  
**Location ID: 311296**



**Photo 21 TB berm is overrun with dead undesirable vegetation.**



**Photo 22 TB overrun with dead undesirable vegetation & trash.**