

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Crow Valley 31-18 Pad

Loc ID: 440344

Inspection: 697505024



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G

CA: This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 06/08/2021. The well location has some evidence of reclamation activities with evidence of few perennial grasses germinating on location. Operator has failed to reclaim the access road and the well location area is dominated by Russian thistle, kochia and bare soil patches. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: ECMC Inspector noted that they were unable to access the site and used historical data to assist with the inspection. Operator then reported that the location has been reclaimed (re-seeded and bare areas addressed) and shared photos from the EcoPoint Assessment completed on November, 8th 2023 to show that the location is in compliance with Rule 1004.