

Operator: BONANZA CREEK ENERGY

Location Name: ANTELOPE 18I TB

Loc ID: 418173

Inspection: 696305524



Exhibit A



Exhibit B



Exhibit C

CA: All 3 Wellhead Signs have faded Well Information is no longer visible; see photos Install sign to comply with Rule 605.d.

CA Resolution: Signs have been installed to comply with Rule 605.d.