

# Interim and Stormwater Inspection

December 5 , 2023

Operator: Crestone Peak Resources Operating- #10633

Location ID: 430346

Inspection Document #: 709400707

Arapahoe County, CO

NENE Section 3 T5S R64W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Tebo 3 1H  
Location ID: 430346



**Photo 1.** Photo taken of location sign, facing east.



**Photo 2.** Photo taken of well on site. Photo taken facing west.



Inspection Photos  
Location Name: Tebo 3 1H  
Location ID: 430346

Dec 5, 2023 at 12:46:28 PM  
3001–3099 S Manilla Rd  
Watkins CO 80137  
United States



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing east.

Dec 5, 2023 at 12:47:20 PM  
3001–3099 S Manilla Rd  
Watkins CO 80137  
United States



**Photo 4.** Photo taken of mowed vegetation on cut slope area. Photo taken facing north.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400707



Inspection Photos  
Location Name: Tebo 3 1H  
Location ID: 430346

Dec 5, 2023 at 12:47:24 PM  
3001-3099 S Manilla Rd  
Watkins CO 80137  
United States



**Photo 5.** Photo taken of revegetated cut slope and berm around working pad. Photo taken facing northwest.

Dec 5, 2023 at 12:48:59 PM  
Watkins CO 80137  
United States



**Photo 6.** Photo taken of revegetated interim area. Photo taken facing southwest.



Inspection Photos  
Location Name: Tebo 3 1H  
Location ID: 430346

Dec 5, 2023 at 12:50:12 PM  
Watkins CO 80137  
United States



**Photo 7.** Photo taken of re-vegetated area with weeds (russian thistle). Photo taken facing north.

Dec 5, 2023 at 12:50:21 PM  
Watkins CO 80137  
United States



**Photo 8.** Photo taken of re-vegetated area with weeds (russian thistle). Photo taken facing northwest.