

# Interim and Stormwater Inspection

December 5 , 2023

Operator: Axis Exploration, LLC - #10646

Location ID: 320788

Inspection Document #: 709400711

Arapahoe County, CO

SWNE Section 29 T4S R63W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR Bennett 16-20  
Location ID: 320788



**Photo 1.** Photo taken of location sign, facing east.



**Photo 2.** Photo taken of well on site. Photo taken facing west.

**Inspection Photos**  
**Location Name: HSR Bennett 16-20**  
**Location ID: 320788**

Dec 5, 2023 at 1:17:17 PM  
45130 E Iliff Trail  
Bennett CO 80102  
United States



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing west.

Dec 5, 2023 at 1:17:29 PM  
45454 E Mexico Ave  
Bennett CO 80102  
United States



**Photo 4.** Photo taken of mowed vegetation in interim reclaimed area. Photo taken facing east.

**Inspection Photos**  
**Location Name: HSR Bennett 16-20**  
**Location ID: 320788**

Dec 5, 2023 at 1:17:48 PM  
45454 E Mexico Ave  
Bennett CO 80102  
United States



**Photo 5.** Photo taken of erosion control blankets, vegetation and weeds (russian thistle) in interim reclaimed area. Photo taken facing northwest.

Dec 5, 2023 at 1:18:07 PM  
45100-45598 E Mexico Ave  
Bennett CO 80102  
United States



**Photo 6.** Photo taken of interim reclaimed area with (russian thistle & Kochia). Photo taken facing south.

Inspection Photos

Location Name: HSR Bennett 16-20

Location ID: 320788

Dec 5, 2023 at 1:20:00 PM  
45454 E Mexico Ave  
Bennett CO 80102  
United States



**Photo 7.** Photo taken of vegetation and weeds (russian thistle, & kochia) in interim reclaimed area. Photo taken facing northeast.

Dec 5, 2023 at 1:20:13 PM  
45100-45598 E Mexico Ave  
Bennett CO 80102  
United States



**Photo 8.** Photo taken of pad with weeds (russian thistle). Photo taken facing southwest.