

Interim and Stormwater Inspection

December 8, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 317891

Inspection Document #: 709400713

Weld County, CO

SWNE Section 6 T2N R66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sakata Robert GU 1
Location ID: 317891

Dec 8, 2023 at 10:06:00 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 1. Photo taken of location sign at wellhead, facing north.

Dec 8, 2023 at 10:06:11 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 2. Photo taken of tank battery on pad. Photo taken facing north.

Inspection Photos
Location Name: Sakata Robert GU 1
Location ID: 317891

Dec 8, 2023 at 10:07:06 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 3. Photo taken of weeds (russian thistle) on site. Photo taken facing south.

Dec 8, 2023 at 10:07:15 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 4. Photo taken of weeds (russian thistle) on site. Photo taken facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400713

Inspection Photos
Location Name: Sakata Robert GU 1
Location ID: 317891

Dec 8, 2023 at 10:07:35 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 5. Photo taken of equipment on site and weeds (russian thistle).. Photo taken facing south.

Dec 8, 2023 at 10:07:52 AM
12587 County Road 24 1/2
Fort Lupton CO 80621
United States



Photo 6. Photo of Weeds (russian thistle) under equipment.. Photo taken facing west.