

WELL NAME: APACHE CANYON 26-16V, API #: 071-07558, INSP. # 695109002



PHOTO 1: LOCATION



PHOTO 2: WELLHEAD AND EQUIPMENT



PHOTO 3: COMPRESSOR





PHOTO 4: AREA OF IMPACTED SOIL APPEARS TO BE FROM SEPARATOR DRAIN (APPEARS THAT HOSE CONNECTING SEPARTAOR DRAIN TO 25 BBL TANK WAS REMOVED). DISCONTINUE DRAINING SEPARATOR IN GROUND, Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 2-3-2024.

