

## Inspection Photos

**Location Name:** ROUSE USX AB-67N64W/31NENE

**Location #:** 302560



Colorado Energy & Carbon Management Commission  
Weld County  
+40.535710,-104.585198  
195° S  
2024-01-05 14:05

**Photo #1**

**Rouse USX AB 31-01 (123-29401) Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement-Surface**



Colorado Energy & Carbon Management Commission  
Weld County  
+40.535854,-104.585314  
193° S  
2024-01-05 14:09

**Photo #2**

**Rouse USX AB 31-01 Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement-Surface**

*Site safety signage*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Location Name: ROUSE USX AB-67N64W/31NENE  
Location #: 302560



Colorado Energy & Carbon Management Commission  
Weld County  
+40.536742, -104.584764  
231° SW  
2024-01-05 14:10

Photo #3

Rouse USX AB 31-01 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-Surface

Wellsite entrance

Photo #4

Rouse USX AB 31-01 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-Surface

JSA: 2024-01-05





## Inspection Photos

Location Name: ROUSE USX AB-67N64W/31NENE

Location #: 302560



**Photo #5**

**Rouse USX AB 31-01 Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement-Surface**

*Battery sign*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources