

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1715 From entrance to location



Photo # 1716 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379




Photo # 1717 Location



Photo # 1718 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1719 Location



Photo # 1720 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Jan 4, 2024 at 11:04:30 AM
CO

Photo # 1721 Location



Jan 4, 2024 at 11:05:54 AM
CO

Photo # 1722 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1723 Location



Photo # 1724 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1725 Debris



Photo # 1726 Unused equipment

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1727 Unused equipment – ECD disconnected



Photo # 1728 Unused equipment – ECD disconnected



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources