

Inspection Photos
Location Name: Wells Ranch USX AE07-66-1HN PAD
Location ID: 429016



Photo 1 – Gas Lift Injection Meter House



Photo 2 – East Wellheads

Inspection Photos
Location Name: Wells Ranch USX AE07-66-1HN PAD
Location ID: 429016



Photo 3 – Wrong Section 18 on Wellhead Signs



Photo 4 – Wrong Section 18 on Wellhead Signs

Inspection Photos
Location Name: Wells Ranch USX AE07-66-1HN PAD
Location ID: 429016



Photo 5 – Wrong Section 18 on Wellhead Signs

Photo 6 – Wrong Section 18 on Wellhead Signs

Inspection Photos
Location Name: Wells Ranch USX AE07-66-1HN PAD
Location ID: 429016



Photo 7 – West Wellheads



Photo 8 – Wellhead Sign