

Final Reclamation Inspection

December 28th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325534

Inspection Document #: 714000279

La Plata County, CO

Township: NENE 16 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MW Johnson A2
Location ID: 325534

12/28/23
+37.194658,-107.718686
88° E



Photo 1. View of the well disturbance from the entrance facing center.



Inspection Photos
Location Name: MW Johnson A2
Location ID: 325534



Photo 2. View of rill/gully erosion forming on the western edge of the disturbance. Current round river rock stormwater BMPs are not adequate.

API #: 067-06566

Inspection Photos
Location Name: MW Johnson A2
Location ID: 325534



12/28/23
+37.195001,-107.718874
80° E

Photo 3. View of the northern interim reclamation area facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06566

Inspection Photos
Location Name: MW Johnson A2
Location ID: 325534



Photo 4. View of reference pasture area comprised of grazed intermediate wheatgrass.

