

Final Reclamation Inspection

December 28th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333767

Inspection Document #: 714000280

La Plata County, CO

Township: NWSW 15 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCaw 34-15 2, 4
Location ID: 333767

12/28/23
+37.187694,-107.713509
81° E



Photo 1. View of the well disturbance from the entrance facing center.



Inspection Photos

Location Name: McCaw 34-15 2, 4

Location ID: 333767



Photo 2. View of gully erosion forming in the southern edge of the disturbance.

API #: 067-08950, 09563

Inspection Photos
Location Name: McCaw 34-15 2, 4
Location ID: 333767



Photo 3. View of surface owner trailer and trash/debris observed stored on location.

API #: 067-08950, 09563

Inspection Photos
Location Name: McCaw 34-15 2, 4
Location ID: 333767



Photo 4. View of the eastern interim reclamation area facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08950, 09563

Inspection Photos
Location Name: McCaw 34-15 2, 4
Location ID: 333767



Photo 5. Reference area comprised of indian rice grass, sagebrush and juniper.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08950, 09563