

Inspection Photos

1/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334619

Inspection Doc: 696205503

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 1: Photos 1-2 taken the western end of the working pad surface. Photos provide an overview of the Location from northwest, north, east to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 3: Photo taken from the west end of the working pad surface, next to the electrical equipment. Photo shows unused/uncapped pipe equipment remaining at the WPS surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 4: Photo taken from the separator equipment on the east end of the Location. Photo shows sinkhole. Sinkhole is ~1.5' wide and 2.5' deep.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 5: Unused flowline heating insulator.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 6: Photo taken from the stockpile berm on the east end of the Location. Though desirable perennial vegetation is apparent, uniform establishment has not been achieved with Undesirable Plant Species, such as cheatgrass, being dominant along the slopes and top of the berm.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334619



Photo 7: Photo taken from the western interim areas of the Location. Photo example of areas where Reclamation has met 1003 Standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources