



RADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 075 - 6540		LEASE NAME: Henderson 3	
LOCATION: NENW 18-9N-53W		OPERATOR: Walsh	
DATE: 7-19-97		INSPECTOR: Ed Binkley (970) 8424465	
Insp. Type: ID	Insp. Status: TA	PA: Y N	Pass/Fail: P F
		Viol.: Y N	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	<i>te</i>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)	<i>Western Services - MIREU to plug</i>	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: *Finish plugging and restore site*

Date Corrective Action Required By: *1-19-98*

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.