

Inspection Photos

1/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334610

Inspection Doc: 696205507

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



Photo 1: Photos 1-2 taken from the eastern interim areas of the Location. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



January 5, 2024



January 5, 2024



January 5, 2024

Photo 3: Photos examples of Noxious Weeds observed within the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



January 5, 2024



January 5, 2024

Photo 4: Working Pad Surface lacks stabilization; BMPs to minimize erosion, degradation and sediment transport missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



January 5, 2024



January 5, 2024

Photo 5: Working Pad Surface lacks stabilization; BMPs to minimize erosion, degradation and sediment transport missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



January 5, 2024



January 5, 2024

Photo 6: Unused equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



Photo 7: Corrosion observed at the base of the southern Produced Water / Condensate Tank; fluids appear to be leaking from these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334610



Photo 8: Photos examples showing holes observed within the liner at the tank battery.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources