

Inspection Photos
Location Name: Wells Ranch USX AA 15-17
Location ID: 306637



Photo 1 – Wellhead



Photo 2 – Unused Fence Posts

Inspection Photos
Location Name: Wells Ranch USX AA 15-17
Location ID: 306637



Photo 3 – Unmarked OOSLAT 1” Riser