

Inspection Photos  
Location Name: Guildner 2  
Location ID: 311318



Photo 1 Location



Photo 2 Dead vegetation and trash by the WH Sign.



**Inspection Photos**  
**Location Name: Guildner 2**  
**Location ID: 311318**



**Photo 3 WH.**



**Photo 4 Dead vegetation around the Ancillary Equip.**



**Inspection Photos**  
**Location Name: Guildner 2**  
**Location ID: 311318**



**Photo 5 Dead vegetation inside the WH fencing.**



**Photo 6 Dead vegetation inside the WH fencing.**

**Inspection Photos**  
**Location Name: Guildner 2**  
**Location ID: 311318**



**Photo 7 Dead vegetation inside the WH fencing.**