

**Operator: EXTRACTION OIL & GAS INC**  
**Location Name: ALMQUIST-62N69W 35SWSW**  
**Loc ID: 321347**  
**Inspection: 702402808**



**Exhibit A**

**CA:** Sign is peeling. Install sign to comply with Rule 605.g.

**CA Resolution:** Operator has reported that signage has been appropriately replaced to comply with Rule 605.g.