

Operator: EXTRACTION OIL & GAS INC
Location Name: ALMQUIST-62N69W 35SESE
Loc ID: 321277
Inspection: 702402806



Exhibit A

CA: Sign is peeling. Install sign to comply with Rule 605.g.

CA Resolution: Operator has reported that signage has been appropriately replaced to comply with Rule 605.g.