

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403653342

Date Received:

01/12/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202866

Inspection Date: 06/25/2021

FIR Submit Date: 06/29/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335573

Location Name: N. Parachute Number: EF G29 595 County: _____

Qtrqtr: SWNE Sec: 29 Twp: 5S Range: 95W Meridian: 6

Latitude: 39.585810 Longitude: -108.074280

FACILITY - API Number: 05-045- -00 Facility ID: 335573

Facility Name: N. Parachute Number: EF G29 595

Qtrqtr: SWNE Sec: 29 Twp: 5S Range: 95W Meridian: 6

Latitude: 39.585810 Longitude: -108.074280

CORRECTIVE ACTIONS:

1 CA# 152322

Corrective Action: Submit documentation and demonstration of compliance with the 1/5/2017 COGCC NTO for Interim Reclamation Procedures for Delayed Operations, this would include estimates for removal, transport and disposal in addition to the cost to perform interim reclamation.

Date: 07/01/2017

Operator shall submit the required documentation attached to a Form 4 to NW EPS Arauza, and NW Reclamation Specialist Trujillo.

Response: CA COMPLETED

Date of Completion: 01/11/2024

Supplemental Form 27 Doc # 403369784 was approved on 05/24/2023 allowing for the excavation and onsite staging of cuttings material from the interim reclamation area. The excavation, stabilization, and compliance

Operator Comment: sampling was completed in 2023 for approximately 7,000 cubic yards of material. Compliant samples were provided to the CECMC on Supplemental Form 27 Doc # 403594398 and backfill was approved under this document and Form 4 Beneficial Reuse Plan Doc # 403595967. Confirmation sampling and closure of the project will be completed following excavation backfill. Interim reclamation and backfill is complete.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 1/12/2024 12:08:04 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files