

Inspection Photos

Loc: 440889

Operator: BAYHORSE PETROLEUM LLC

Inspection Date: 1/10/2024

County: KIOWA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The perimeter fence has been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Loc: 440889 | Date: 1/10/2024

Inspection Photos



Photo 2. Facing east at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 440889 | Date: 1/10/2024

Inspection Photos



Photo 3. Facing west at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Loc: 440889 | Date: 1/10/2024