

Inspection Photos

Loc: 440886

Operator: BAYHORSE PETROLEUM LLC

Inspection Date: 1/10/2024

County: KIOWA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road. This area has wind blown out but most of the road has become a two track.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 440886 | Date: 1/10/2024

Inspection Photos



Photo 2. Facing east toward the location. The perimeter fence has been removed..



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Loc: 440886 | Date: 1/10/2024

Inspection Photos



Photo 3. Facing north at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 440886 | Date: 1/10/2024

Inspection Photos



Photo 4. Center of the location facing south.

