

Inspection Photos

Loc: 307914

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/16/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northeast along the access road.



Inspection Photos




Photo 2. Facing northwest toward the wellsite.



Inspection Photos



Photo 3. The location fence at the north side is down and needs maintenance.

