

# Inspection Photos

Loc: 307906

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/16/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307906 | Date: 1/16/2024



## Inspection Photos



**Photo 2.** Facing north toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307906 | Date: 1/16/2024



## Inspection Photos



**Photo 3.** There is ice build up from a dripping leak at the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307906 | Date: 1/16/2024