

Inspection Photos
Location Name: Sydney Strear 2
Location ID: 318046



Photo 1 Location



Photo 2 WH Sign.

Inspection Photos
Location Name: Sydney Strear 2
Location ID: 318046



Photo 3 Dead vegetation and debris by the WH.



Photo 4 Trash/Bent rod.

Inspection Photos
Location Name: Sydney Strear 2
Location ID: 318046



Photo 5 Dead vegetation by the ancillary equip.



Photo 6 dead vegetation by the Pump Jack.