

Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325672

Inspection Document #: 714000312

La Plata County, CO

Township: NESW 36 34N 12W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Payne Schmitt 1
Location ID: 325672

1/17/24
+37.145905,-108.103442
294° NW



Photo 1. View of the disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06814

Inspection Photos
Location Name: Payne Schmitt 1
Location ID: 325672



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the associated tank battery from the southern edge facing northwest.

API #: 067-06814

Inspection Photos
Location Name: Payne Schmitt 1
Location ID: 325672



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Weedy debris observed around equipment.

API #: 067-06814

Inspection Photos
Location Name: Payne Schmitt 1
Location ID: 325672



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Corrective action from inspection doc #687905155 has been addressed. 55 gallon drum drain plug has been installed.

API #: 067-06814

Inspection Photos
Location Name: Payne Schmitt 1
Location ID: 325672



1/17/24
+37.146107,-108.103363
167° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Interim reclamation vegetation was not fully assessed due to snowy conditions. Rabbitbrush observed in snowy areas.

API #: 067-06814