

# Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325651

Inspection Document #: 714000313

La Plata County, CO

Township: NWSE 36 34N 12W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Schmitt 3-36  
Location ID: 325651



Photo 1. View of the disturbance from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06775



Inspection Photos  
Location Name: Schmitt 3-36  
Location ID: 325651



**Photo 2.** View of weedy debris around equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06775



Inspection Photos  
Location Name: Schmitt 3-36  
Location ID: 325651



**Photo 3.** View of stained soils around the well head.

Inspection Photos  
Location Name: Schmitt 3-36  
Location ID: 325651

1/17/24  
+37.146005,-108.099234  
208° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Interim vegetation was not fully assessed due to the snowy conditions.

API #: 067-06775