

Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325567

Inspection Document #: 714000315

La Plata County, CO

Township: SENW 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist




COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: M&M 2
Location ID: 325567



1/17/24
+37.134908,-108.103071
206° SW

Photo 1. View of the disturbance from the entrance facing center.



1/17/24
+37.134823,-108.103128
336° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06623

Inspection Photos
Location Name: M&M 2
Location ID: 325567

1/17/24
+37.134903,-108.103206
273° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Interim reclamation was not fully assessed due to snowy conditions.

API #: 067-06623