

# Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325568

Inspection Document #: 714000316

La Plata County, CO

Township: NWSW 1 33N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: M&M 3  
Location ID: 325568



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos  
Location Name: M&M 3  
Location ID: 325568



**Photo 2.** Weedy debris observed around equipment.

Inspection Photos  
Location Name: M&M 3  
Location ID: 325568



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of the unused equipment observed on the eastern edge of the disturbance.

API #: 067-06624