

Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325677

Inspection Document #: 714000318

La Plata County, CO

Township: NENE 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Angelina 8
Location ID: 325677



Photo 1. View of the disturbance from the entrance facing center.



API #: 067-06821



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Angelina 8
Location ID: 325677

1/17/24
+37.138481,-108.094324
84° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of wood pallet debris observed around active equipment.

API #: 067-06821

Inspection Photos
Location Name: Angelina 8
Location ID: 325677



Photo 3. View of unused piping observed on the western edge of the disturbance.

Inspection Photos
Location Name: Angelina 8
Location ID: 325677

1/17/24
+37.138405,-108.094242
40° NE



Photo 4. Interim vegetation was not fully assessed due to snowy conditions.

