

Final Reclamation and Stormwater Inspection

Date: 01/12/2024

Operator: CARRIZO NIOBRARA LLC - 10439

Location ID: 405896

Inspection Document #: 708200878

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State 1-36
Location ID: 405896



Photo 1. The well location is not progressing towards Rule 1004 standards with bare soils and debris observed.

Inspection Photos
Location Name: State 1-36
Location ID: 405896



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: State 1-36
Location ID: 405896



Photo 3. See comments in Photo 1.