

Interim Reclamation Inspection

Date: 01/12/2024

Operator: BISON IV OPERATING LLC - 10670

Location ID: 447902

Inspection Document #: 708200881

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 1. Southern interim areas, facing south. The interim areas are predominantly undesirable vegetation (e.g. russian thistle and kochia). It does not appear the location has been actively managed for weed control during the previous growing season. Additional reclamation activities are required.

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 2. Eastern interim areas, facing west. See comments in Photo 1.

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photos 3 & 4. Northern interim areas, facing northwest and east. See comments in Photo 1.

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 5. Southwest interim areas, near the entrance. See comments in Photo 1.

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 6. Taken from the western side of the location. The left side of the fence is undisturbed reference area with native, perennial vegetation. The right side of the fence is the location with undesirable vegetation that is not reflective of the reference areas.

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 7. Taken south of the location. The red polygon illustrates the location and predominant weedy vegetation cover (darker vegetation).

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo 8. Google Earth aerial imagery (circa 11/2023) illustrating significant weed cover (darker vegetation).

Inspection Photos
Location Name: Shull Pad 9-59-31
Location ID: 477902



Photo s 9 & 10. No emergency contact information at wells.