

Inspection Photos

1/22/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334742

Inspection Doc: 696205554

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334742



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest and northwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334742



January 22, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334742



Photo 3: Photo taken from the top of the topsoil stockpile, on the east end of the Location, facing south. Photo is an example showing areas of the stockpile that are predominantly bare and exposed soils. Photo also show what appears to be “pea-gravel” placed on top of the stockpile.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334742



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources