

Inspection Photos

1/22/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 324070

Inspection Doc: 696205556

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324070



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324070



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324070



Photo 3: Photos examples showing vegetation/weed debris accumulation within the secondary containment measure at the battery facility. .



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324070



Photo 4: Unused corrugated flex-pipe.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324070



Photo 5: Photos examples of unmarked anchors observed on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources