

Final Reclamation Inspection

Date: 1/19/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 441481

Inspection Document #: 713900291

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: State Seventy Holes P-6 Pad

Location ID: 441481



Photo 1. The photo was taken at the abandoned well location facing North. The photo illustrates the location has not been built.



Photo 2. The photo was taken at the abandoned well location facing East. Refer to the comment for photo 1.

Inspection Photos

Location Name: State Seventy Holes P-6 Pad

Location ID: 441481



Photo 3. The photo was taken at the abandoned well location facing South. Refer to the comment for photo 1.




Photo 4. The photo was taken at the abandoned well location facing West. Refer to the comment for photo 1.