

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317




Photo # 3546 From entrance to location



Photo # 3547 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317




Photo # 3548 Location




Photo # 3549 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 3550 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife