

# Final Reclamation Inspection

January 22nd, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325405

Inspection Document #: 714000330

La Plata County, CO

Township: NWNE 12 33N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hazel 2  
Location ID: 325405



**Photo 1.** View of the disturbance from the entrance facing center.





Inspection Photos  
Location Name: Hazel 2  
Location ID: 325405



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of eastern interim reclamation area facing south.  
Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-06324

Inspection Photos  
Location Name: Hazel 2  
Location ID: 325405

1/22/24  
+37.124141,-108.098734  
285° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of unused equipment observed at the well disturbance.

API #: 067-06324



Inspection Photos  
Location Name: Hazel 2  
Location ID: 325405



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of associated tank battery facing southeast.

API #: 067-06324



Inspection Photos  
Location Name: Hazel 2  
Location ID: 325405



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of fence post, barb wire, and weedy debris observed within the tank battery berm.

API #: 067-06324