

# Inspection Photos

API: 043-06194

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/18/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 1/18/2024



## Inspection Photos



**Photo 2.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 1/18/2024



## Inspection Photos



**Photo 3.** Facing back northwest. There is an offsite tank battery shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 1/18/2024



## Inspection Photos



**Photo 4.** Standing at the tank battery facing south. The well is shown at red arrow. The flowline does not appear to be registered.





## Inspection Photos



**Photo 5.** Facing southwest toward the offsite tank battery which has 6 tanks. There is not a proper sign posted at the tank battery.







**Photo 4.** Facing south at the west side of the location. There is an exposed electric line at red arrow and multiple open pipe risers. All risers and utilities need to be removed. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:417859 | Date: 1/18/2024