

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: North Platte T-23 Pad

Loc ID: 470863

Inspection: 713900191



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Weed debris in the form of tumbleweeds were observed across the well location. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606 to remove weed debris.

CA Resolution: Operator has addressed the identified weed debris to assist with preventing the spread of weeds on location and comply with Rule 606. Location has also been reseeded and straw crimped to assist with promoting vegetation.

CA: Soil sedimentation has buried a portion of the perimeter fencing of the well location and rendered the fencing in that corner useless. Comply with Rule 603.h. to maintain perimeter fencing.

CA Resolution: Operator has addressed and repaired perimeter fencing to comply with Rule 603.h.