

Inspection Photos
Location Name: UPRR 42 Pan Am AE 1
Location ID: 318233



Photo 1 Location

Photo 2 WH Sign.

Inspection Photos
Location Name: UPRR 42 Pan Am AE 1
Location ID: 318233



Photo 3 WH

Photo 4 Ancillary Equipment.

Inspection Photos
Location Name: UPRR 42 Pan Am AE 1
Location ID: 318233



Photo 5 Stained soil approx. 15 ft. from the WH.

Photo 6 Stained soil approx. 15 ft. from the WH.

Inspection Photos
Location Name: UPRR 42 Pan Am AE 1
Location ID: 318233



Photo 7 Stained soil approx. 15 ft. from the WH.

Photo 8 Stained soil approx. 15 ft. from the WH.

Inspection Photos
Location Name: UPRR 42 Pan Am AE 1
Location ID: 318233



Photo 9 Wellsite.