

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34-12A Pad

Location # 334179



Photo # 3564 From entrance to location



Photo # 3565 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34-12A Pad

Location # 334179




Photo # 3566 Location



Photo # 3567 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34-12A Pad

Location # 334179



Photo # 3568 Location



Photo # 3569 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34-12A Pad

Location # 334179




Photo # 3570 Location




Photo # 3571 Two wellheads missing signs/lack required signage

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34-12A Pad

Location # 334179



**Photo # 3572 Two wellheads missing signs/lack required signage**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources